Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	9	((paper near5 curl) near3 (test$5 detect$5 sens$5 estimat$5 identif$6 evaluat$5 determin$5 measur$5 transducer cell meter gauge monitor$5)).clm.	USPAT; EPO; JPO	OR	ON	2005/01/25 16:39
L2	5	unbonded near3 capping	USPAT; EPO; JPO	OR	ON	2005/01/25 16:58
L3	14	(("6591691") or ("4740025") or ("4445387") or ("3545263") or ("2414559")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/01/25 16:57
L4	485	compression near2 pad$5.clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:10
L5	6	4 and (unbonded capping)	USPAT; EPO; JPO	OR	ON	2005/01/25 16:59
L6	2	4 and concrete.clm.	USPAT; EPO; JPO	OR	ON	2005/01/25 16:59
L7	10	(compression near2 pad$5) near3 (grip$5 nub protrusion groove appendage stick$5 grab$5) .clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:16
L8	50	(compression near2 pad$5) near3 (grip$5 nub protrusion groove appendage stick$5 flap$5 wing grab$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:21
L9	0	(compression near2 pad$5) near3 (fall$6 drop$5).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:21
L10	0	(compression near2 pad$5) near6 (fall$6 drop$5).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:21
L11	9	(compression near2 pad$5) near6 (fall$6 drop$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:23

L12	5264	(prevent$5near4 pad$5) near4 (fall$6 drop$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:23
L13	400	(prevent$5 near4 pad$5) near4 (fall$6 drop$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:24
L14	23	(prevent$5 near4 pad$5) near4 (fall$6 drop$5).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/01/25 17:24